PROSTOR X-RACK

Assembly Instructions

Material list





Slide small end of Legs into Torso, taking care to align screw holes. Secure with 4 short screws and nuts, as shown. Secure balance bracket with 6 short screws and nuts, as shown.



Slide small end of Arms into Torso, taking care to align screw holes.

Align screw holes of Net Bracket with those in frame. Attach bracket with 4 long screws and nuts, as shown.

Align screw holes of Boot, Shoe, Skate Shelf with those in legs. Attach with 4 short screws and nuts, as shown.



Align screw holes of Upper Basket with those in frame. Attach basket with 4 short screws and nuts, as shown.

Slide Tube Caps into ends of all tubing (6 places) as shown.

Slide loops of Upper Net over outermost rungs of arm hooks, as shown. Repeat procedure for Lower Net.

Total weight not to exceed 50 pounds

Need Help? Call 800-783-7725,
ProStor a division of Racor, Inc.
Sandpoint, Idaho

Warranty
This equipment is warranted to be free of defects in material and workmanship for a period of one year form the date of purchase. Should any part of this equipment be defective, it will be repaired or replaced at the seller's option free of charge (except shipping fees). Proof of purchase must be submitted to Racor, Inc. to obtain the benefits of this warranty. The warranty is void if: The equipment has been damaged by negligence, accident or mishandling, or has not been used in accordance with the seller's recommendation or has been altered or repaired by persons other than Racor, Inc. No other warranty express or implied including merchantability applies to this product. Racor, Inc. does not assume any responsibility for consequential damages occasioned by the product, or inconvenience. Certain states prohibit limitation of warranties. You may have certain additional rights in some states.